



### CINTA GUIA EM METRO

	MEDIDA	MATERIAL
GUIA	2,5 X 1,5	PTFE + Bronze
GUIA	3,0 X 1,5	PTFE + Bronze
GUIA	3,5 X 2,0	PTFE + Bronze
GUIA	4,0 X 1,5	PTFE + Bronze
GUIA	5,0 X 2,0	PTFE + Bronze
GUIA	5,5 X 2,5	PTFE + Bronze
GUIA	6,0 X 2,0	PTFE + Bronze
GUIA	6,0 X 2,5	PTFE + Bronze
GUIA	6,3 X 3,0	PTFE + Bronze
GUIA	6,5 X 3,5	PTFE + Bronze
GUIA	7,91 X 1,5	PTFE + Bronze
GUIA	9,0 X 2,0	PTFE + Bronze
GUIA	9,5 X 2,0	PTFE + Bronze
GUIA	9,5 X 2,5	PTFE + Bronze
GUIA	9,5 X 3,0	PTFE + Bronze
GUIA	9,6 X 2,5	PTFE + Bronze
GUIA	12 X 2,5	PTFE + Bronze
GUIA	12,7 X 2,0	PTFE + Bronze
GUIA	12,7 X 2,5	PTFE + Bronze
GUIA	12,7 X 2,7	PTFE + Bronze
GUIA	12,7 X 3,0	PTFE + Bronze
GUIA	12,7 X 4,0	PTFE + Bronze
GUIA	15,0 X 2,5	PTFE + Bronze
GUIA	15,0 X 3,0	PTFE + Bronze
GUIA	15,0 X 4,0	PTFE + Bronze
GUIA	20,0 X 2,5	PTFE + Bronze
GUIA	20,0 X 3,0	PTFE + Bronze
GUIA	20,0 X 4,0	PTFE + Bronze
GUIA	22,0 X 2,0	PTFE + Bronze
GUIA	25,0 X 2,5	PTFE + Bronze
GUIA	25,0 X 3,0	PTFE + Bronze
GUIA	25,4 X 4,0	PTFE + Bronze

Verificar disponibilidade em estoque

Para medidas não relacionadas, favor consultar nosso televendas.